SOCIEDAD IMPORTADORA MARITEX SPA
AVENIDA EL SALTO 1979,RECOLETA,SANTIAGO,CHILE

The following sample(s) was/were submitted and identified on behalf of the client as:

Sample Description	:	(A)Woven fabric (70D*160D 240T 100%Nylon 0.15mm*0.15mm Ripstop Taslon with TPU Milky Membrane)
Buyer	:	SOCIEDAD IMPORTADORA MARITEX SPA
Brand	:	MARITEX
Sample Color	:	(A)ROYAL BLUE
Composition	:	(A)100% Nylon
Fabric Width	:	(A)148CM
Fabric Weight	:	(A)140g
Style No.	:	93
Order No.	:	#1326
Season	:	WINTER
Supplier	:	
Origin	:	China
Destination	:	Chile
Proposed Care Instruction	:	Maximum washing termperature 30 degree,normal process. Do not bleach Do not dry clean Iron on low heat
Sample Receiving Date	:	Apr 20, 2026
Testing Period	:	Apr 20, 2026 - Apr 23, 2026
Test Result(s)	:	Unless otherwise stated the results shown in this test report refer only to the sample(s) tested, for further details, please refer to the following page(s).
Test Performed	:	Selected test(s) as requested by applicant

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Shanghai) Co., Ltd

Jojo Cai

Jojo Cai (Authorized Signatory)

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

3rd Building,No.889,Yishan Road,Xuhui District Shanghai,China 200233 t (86-21) 61402666 f (86-21) 64958763 www.sgsgroup.com.cn
中国·上海·徐汇区宜山路889号3号楼 邮编: 200233 t (86-21) 61402666 f (86-21) 64958763 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

Test Result

Water Vapour Transmission*

(ASTM E96-95;Test Condition: Procedure BW - Inverted Water Method at 73.4°F (23°C) & 50±2% RH; Orientation: Back Side Facing To Water)

As Received

-	Unit	**A**
Water Vapour Transmission	g/24h/m²	6982

*** This test was carried out by SGS-CSTC Standards Technical Services (Changzhou) Co., Ltd**

Sample Photo



End of Report

Scan to see the report

SL52605309195101TX

Verification:
check.sgsonline.com.cn

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

3rd Building,No.889,Yishan Road,Xuhui District Shanghai,China 200233 t (86-21) 61402666 f (86-21) 64958763 www.sgsgroup.com.cn
中国·上海·徐汇区宜山路889号3号楼 邮编: 200233 t (86-21) 61402666 f (86-21) 64958763 sgs.china@sgs.com

Member of the SGS Group (SGS SA)