

REPORT NUMBER:

HGHT08147250



TEST REPORT

Number : HGHT08147250

Applicant :

Date : Oct 09, 2024

Sample Description As Declared :


No. Of Sample : One (1)  
Fibre Content : 85%C 15%P  
Material : Knitted CVC Fleece Fabric  
Finishing : -  
End Uses : -  
Colour : Grey  
Style No. : FC24082401  
Order No./PO No. : -  
Buyer's Name : -  
Manufacturer's Name : -  
Ref. : -

Applicant's Provided Care Instruction/Label :

-

Date Sample Received : Aug 29, 2024  
Date Testing Started : Aug 29, 2024

Prepared And Checked By:  
For Intertek Testing Services Ltd., Hangzhou



Vivian Zhao  
Manager



**Intertek Testing Services Ltd., Shanghai, Hangzhou Branch**

2F, 3F, 4F, 6F's Room 601-618, Building 6, No. 1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China

上海天祥质量技术服务有限公司杭州分公司

中国浙江省杭州市滨江区长河街道滨安路 1180 号 6 幢 2 层、3 层、4 层、6 层 601-618 室 邮编:310052

Tel: +86 571 8768 8218 Fax: +86 571 8679 0296

E-mail: hztml@intertek.com

Attention is drawn to the terms and conditions on Website:

[www.intertek.com.cn/responsibility](http://www.intertek.com.cn/responsibility)

TEST REPORT

Number : HGHT08147250

Tests Conducted (As Requested By The Applicant)

1 Fabric Propensity to Surface Pilling, Fuzzing or Matting As Received (ISO 12945-1:2020, Pilling Box Method):

Revolutions	Mean Grade		
	Pilling	Fuzzing	Matting
10800	4	4	4-5

Remark:

The visual assessment of pilling, fuzzing and matting was carried out respectively according to ISO 12945-4.

---

End of Report

*This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.*

*This report shall not be reproduced except in full, without written approval of the laboratory.*

**Intertek Testing Services Ltd., Shanghai, Hangzhou Branch**

2F, 3F, 4F, 6F's Room 601-618, Building 6, No. 1180, Bin'an Road, Changhe Street, Binjiang District, Hangzhou, Zhejiang, China

**上海天祥质量技术服务有限公司杭州分公司**

中国浙江省杭州市滨江区长河街道滨安路 1180 号 6 幢 2 层、3 层、4 层、6 层 601-618 室 邮编:310052

Tel: +86 571 8768 8218 Fax: +86 571 8679 0296

E-mail: hztml@intertek.com

Attention is drawn to the terms and conditions on Website:

[www.intertek.com.cn/responsibility](http://www.intertek.com.cn/responsibility)